



BRAKES

ENGINEERED SOLUTIONS

Bulletin BES 07-24

Subject: New brake rotor and pad design

Vehicle Involved: 1994 – 2000 Kia Sephia and Spectra

Condition: premature wear on pad and rotor.

Repair Procedure: Due to premature wear the brake rotor vent design has been changed as seen in fig 1. The brake pad surface also has been increased from 37.5 sq. cm to 43.0sq. cm as seen in fig 2

Fig 1



Fig 2



NOTE: The new pads and rotors are interchangeable AS A SET with previous parts

The new pads MUST be used with the new rotors - Do not mix old rotors/pads with new rotors/pads