



***BRAKES***

# ENGINEERED SOLUTIONS

## Bulletin BES 12-03

**Subject:** Brake caliper bracket identification

**Vehicles Involved:** 2002-2005 Chevrolet Trailblazer, 2002-2005 GMC Envoy, 2004-2005 Buick Rainier, Oldsmobile Bravada, Isuzu Ascender

**Condition:** Caliper Bracket

**Repair Procedure:** There are two calipers offered for the above platforms.

Both calipers are physically the same except that the bracket is different.

The change to the bracket was made to accommodate the larger rotor diameter.

The bracket can be easily identified with an even or protruding tab with the bracket.

One other detail is the distance between the mounting holes and the slider pin, the distance is 3 inches as compared to the dimensions of the other bracket with the distance of 3.250".