



**BRAKES**

# ENGINEERED SOLUTIONS

## Bulletin BES 08-09

**Subject:** Squeak Noise coming from the rear of the vehicle over bumps

**Vehicle Involved:** 2006-2007 Ford Focus

**Condition:** On some 2006-2007 Ford Focus vehicles you may get a squeaking noise from the rear of the vehicle going over bumpy conditions. This noise may be coming from the rear cable sleeve rubbing the brake cable bracket located under the vehicle near the rear suspension tie bar being transferred into the vehicle body

### Repair Procedure:

1. remove the parking brake cable bracket bolt
2. Insert the new plastic insert into the square hole used for locating the cable bracket. This will hold the bracket in place and keep it from rubbing the cable sleeve.
3. Remove any existing grease from the cable bracket and sleeve only in this area only
4. install one end of bracket into the new insert and bolt the end on at 17lb-ft  
The Ford part number for the insert is 380707-s

