



BRAKES

ENGINEERED SOLUTIONS

No. BES 09-12

Subject: Brake Pads installation caution

Vehicle Involved: 2000 - 04 Hyundai Santa Fe using FMSI Pad D864-7739

Condition: Inboard and outboard pads look similar and may be installed incorrectly, causing erratic and noisy braking.

Repair Procedure: When installing the pads you must be sure the outboard pad, (see illustrations below), is installed in the correct position. Failure to do so will not allow the pads to seat in the locator holes.

If not installed properly, the pads will vibrate, make noise, and wear prematurely. When installing the new pads, lubricate the ends and the shim area where it makes contact with the caliper housing and/or piston.

