



BRAKES

ENGINEERED SOLUTIONS

Bulletin BES 11-09

Subject: Front Brake Noise In Reverse

Vehicles Involved: 2005 - 2007 model year Tacoma 4x4 and Pre-Runner vehicles

Condition: Some vehicles may experience front brake noise when driving in reverse and applying the brake pedal. The noise will typically occur when backing up after the vehicle has been stopped for an extended period of time. Updated front brake rotors part number 880670, are now available to improve this condition.

Repair: Conduct a road test to confirm the noise condition, the noise typically occurs when backing out of a parking spot in reverse. Remove the front brake pads and front rotors. Apply grease on the brake pads as shown in the dotted area below, and install the front brake pads and front rotors. Road test the vehicle to confirm the front brake noise is no longer present.

