



***BRAKES***

# ENGINEERED SOLUTIONS

## Bulletin BES 01-09

**Subject:** Low brake pedal, brakes may not release.

**Vehicle Involved:** 1999 Buick Park Avenue, Oldsmobile Aurora, 2000 Buick LeSabre

**Condition:** Easy to overlook when diagnosing a low brake pedal. The attachment nuts that secure the brake booster to the pedal Assembly may be loose. Customers may complain of a low brake pedal. If the attaching nuts continue to back off, the condition may result in total brake failure. Water and fume intrusion can also occur in the passenger compartment.

**Repair Procedure:** Mfg. Campaign Number 99038. Dealers will replace any nuts that are missing, and tighten all four of the nuts to the required torque specification.