



BRAKES

ENGINEERED SOLUTIONS

Bulletin BES 11-01

Subject: Front caliper housing bolt

Vehicles Involved: 1987-2002 Dodge Dakota/ Durango

Condition: Caliper housing bolt damaged when servicing front brakes

Repair: When servicing the brakes and replacing the front brake pads some techs have complained that the hex head of the housing bolt because of its size M9-1.25 is easily stripped or damaged when they re-install the caliper.

The fix is to install an alternative housing bolt with a M10-1.25 hex head. The bigger hex will be stronger and will facilitate installation without any issues.

The NAPA Brakes part number for the M10-1.25 housing bolt is 82354W.