



BRAKES

ENGINEERED SOLUTIONS

Bulletin BES 09-03

Subject: Squeaking noise when pressing brake pedal

Vehicle Involved: 2004-2006 Nissan Sentra

Condition: Customer may hear a squeaking noise from under the dash when brakes are applied.

Repair Procedure: If a squeaking noise is heard coming from under the dash, the problem may be in the stop light switch. Verify that the noise is coming from the stop light switch.

If the noise is coming from the switch replace the switch.

When installing stop light switches make sure they are adjusted properly. Improperly adjusted, the stop lamp switch may prevent the brake pedal from returning to it's at rest position, causing the front brakes to over heat.

Nissan replacement switch assembly part number 25320-AX00A