



BRAKES

ENGINEERED SOLUTIONS

Bulletin BES 03-24

Subject: Subaru Forrester Anti Lock Brake Parts (ABS) Catalog Error

Vehicle Involved: 1999 Subaru Forrester

Condition: Vehicles that require replacement of the Electronic ABS control module, technicians should request the Subaru Dealer parts department to reference Parts Bulletin number 31-06-98. A parts catalog error may result in the use of an incorrect ABS control unit.

The use of an incorrect Electronic Brake Control Module (EBCM) may result in additional diagnostic problems. The correct repair for this problem can only be resolved by utilizing the vehicle specific part number.